



# HEARST REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	HEARST RECREATION CENTER	5/26/2016	WS- 011579	Utility	Ground Floor	Exterior (water source)	WT-042916-11596- A	17	WT-042916-11596- B	1.7	Non-drinking water source turned off			
2	HEARST RECREATION CENTER	5/26/2016	WS- 011580	Cooler	1	In rec center	WT-042916-11597- A	< 1	WT-042916-11597- B	< 1				
3	HEARST RECREATION CENTER	5/26/2016	WS- 011581	Fountain	Ground Floor	In turf field Right High	WT-042916-11598- A	< 1	WT-042916-11598- B	< 1				
4	HEARST RECREATION CENTER	5/26/2016	WS- 011582	Fountain	Ground Floor	In turf field Left Low	WT-042916-11599- A	< 1	WT-042916-11599- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.